## S ENVIRONMENTAL PROTECTION AGENCY

vision of Air Pollution Control--Field Operations Section

TE:

October 1, 1990

September 27, 1990 Date of Inspection:

TO:

Sy Levine

Last Insp. Date: \_\_\_\_\_ May 5, 1989

FROM:

William Zenisek

Region/Distirct:

01.06

SUBJECT: Facility:

Alco Steel Service

197 809 ABG I.D. #:

525 Rowell, Joliet, Illinois 60434

Contact/Title: Al Cohn, Owner

Address:

815/723-0661 Phone:

An investigation was made in accordance with the workplan to determine status of the wire burning incinerator at the facility. Inspection of the incinerator was provided by Mr. Cohn, after Mr. Cohn consulted with his attorney, John Parker.

The incinereator was shut down and not accessible for use by the workers. Mr. Cohn blocked-off the incinerator area by piling boxes of scrap in front of it. It appeared that the incinerator had not been in recent use. It was noted that there was a large quantity of insulated aluminum wire at the facility which Mr. Cohn indicated that they would ship to Chicago for stripping and recovering the aluminum.

Mr. Cohn requested written permission from the Agency to remove the incinerator from the facility. I advised Mr. Cohn and his attorney John Parker (via phone) that they should make their request in writing to the Agency to remove the incinerator. I explained that it was my opinion that the incinerator could be removed providing proper precautions were taken to protect the workers and environment. On removal of the incinerator, the facility listing can be deleted from EIS, as there are no other air emission sources at the facility.

BZ:bj:0254j

EPA Region 5 Records Ctr. 283399

## HED TO INSPECTION MEMORANDUMS - FOR INTERNAL USE ONLY!

| Illinois Environmen         | tal Protection Agency · 2200 (  | Churchill Road, Springfield, IL 62706 |
|-----------------------------|---|---------------------------------------|
| (For Internal Use Only)     | Date of Inspect   | ion: Sept. 27, 1990                   |
| in 0                        | I.D.#: /97809   | ABG R/D: 01/06                        |
| Facility: Alco              | Steel Service   |                                       |
| Address: Jolie              | f. Nel. 60434   |                                       |
| Contact/Title()_Al          | Cohn Olmer  | Phone: <u>815-723-666</u> /           |
| PRE-INVESTIGATION STATUS:   |   |                                       |
| <u>x</u> horkplan           | (A)Task Force   | (R)Random/Non-Traditional             |
| Cuarterly Report<br>MIR     | (B)On Program   | (S)HC Chicago/St.Louis                |
| Other                       | (C)Violator<br>(D)NESHAPS   | (T)TSP Chicago/St.Louis<br>(U)A-l     |
|                             | (F)NSPS   | (V)B Facility                         |
|                             | X(1)A-2 00T 111893  | (W)Multi-Media Problems               |
|                             | (J)Special Request  | (X)Service Station                    |
|                             | (M)Asbestos D/Rsut menada .   | (Z)Petrochemical Plant                |
| INSPECTION FINDINGS:        | त त्र क्षेत्र के कि विश्व के कि विश्व<br>विश्व के कि विश्व के कि वि |                                       |
| Emission Violation          | CIL   | X_TAS Checked                         |
| Permit Violation            | To MIR  | TAS Coded                             |
| Permit Condition Violation  | To Quarterly Report   | Form 177 Compliance Flow              |
| XND VIOLATION               | Multi-Media Issue Possible  | Malfunction                           |
| Flag File                   | Land Noise Water  | Copy to Facility                      |
| -                           |   | Frequency Change                      |
| IL532-1244                  |   |                                       |
| APC 421 6/87<br>John Parker | (via phone) that they   | incinerator. I explained that         |
| John Farker                 | he Agency to remove the   | incinerator. I explained browiding    |

John Parker (via phone) that the incinerator. I explained that writing to the Agency to remove the incinerator could be removed providing it was my opinion that the incinerator could be removed providing proper precautions were taken to protect the workers and proper precautions were taken to protect the workers and environment. On removal of the incinerator, the facility listing environment. On removal of the incinerator air emission sources can be deleted from EIS, as there are no other air emission sources at the facility.

BZ:bj:0254j